

May 13, 2020



Laboratory Advisory Board

Alan L. Wozniak, CIAQP
 President/CEO

- Mark D. Wozniak, MBA, CIAQP
 Vice President
- Rajiv Sahay, Ph.D. Laboratory Manager
- Francisco T. Aguirre Building Sciences Manager Certified St. Lic. Class A
- Cynthia M. Bailey
 Business Manager

Robin Lutz Turning Point of Tampa 6227 Sheldon Road Tampa, FL 33615

Re: 6227 Sheldon Road Laboratory Analysis Report Work Authorization # 07146- 025828

Dear Robin Lutz,

We appreciate the opportunity to provide you with our professional indoor environmental laboratory services. The following environmental assays were performed on the samples submitted by you:

• Coronavirus (Covid-19 Virus) - SARS-CoV-2

Please call me at 1-800-422-7873, ext. 301, should you have any questions. We look forward in assisting you to create a healthy indoor environment for you and your organization.

Sincerely,

Reahay.

Dr. Rajiv Sahay, CIAQP, FIAS EDL Laboratory Director



Laboratory Analysis Report "Other" Samples

Client:Turning Point of TampaJobsite:Turning Point of TampaLocation :6227 Sheldon Road

 PACS ID # :
 07146

 Work Order # :
 025828

 Project Date :
 5/12/2020

 Date Issued :
 5/13/2020

Mech. Unit : N/A Zone : Copier Test Site : Keyboard

Sample #	Sample Type	Date	Time	Results	Units	
188348	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:25 pm	Not Detected		

Mech. Unit: N/A

Zone : Group B Test Site : Knob

Sample #	Sample Type	Date	Time	Results	Units
188345	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:12 pm	Not Detected	

Mech. Unit : N/A

Zone : Group Ext

Test Site : Knob, Light switch

Sample #	Sample Type	Date	Time	Results	Units		
188346	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:17 pm	Not Detected			
Mech. Unit							

Zone : Group Room #1

Test Site : Knob, Light switch

Sample #	Sample Type	Date	Time	Results	Units
188350	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:32 pm	Not Detected	

Mech. Unit : N/A

Zone : Kitchen

Test Site : Door Knob, Microwave, Table


Sample #	Sample Type	Date	Time	Results	Units
188347	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:20 pm	Not Detected	

Method of Analysis: EDLab SOP-7-27(RT-qPCR)

1) The result applies to the specific surface from where samples was collected.

2) This test is not for Clinical Diagnostics.

The results in this report apply only to the sample(s) specifically listed above and tested at Environmental Diagnostics Laboratory. Unless otherwise noted, samples were received in good condition. Laboratory-prepared Quality Control (QC) samples are analyzed with the samples routinely; however, unless a blank (control) is received, the result for the control is not compared.





Laboratory Analysis Report "Other" Samples

Client: **Turning Point of Tampa** Jobsite: **Turning Point of Tampa**

Location : 6227 Sheldon Road

 PACS ID # :
 07146

 Work Order # :
 025828

 Project Date :
 5/12/2020

 Date Issued :
 5/13/2020

Mech. Unit : N/A Zone : Lobby

Test Site : Couner, Door Knob

Sample #	Sample Type	Date	Time	Results	Units
188341	SARS-CoV-2/2019 n-CoV-2	5/12/2020	1:48 pm	Not Detected	

Mech. Unit : N/A

Zone : Staffing

Test Site : Door Knob, Light switch

Sample #	Sample Type	Date	Time	Results	Units
188349	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:28 pm	Not Detected	

Mech. Unit : N/A

Zone : Time Clock

Test Site : Buttons

Sample #	Sample Type	Date	Time	Results	Units	
188343	SARS-CoV-2/2019 n-CoV-2	5/12/2020	1:58 pm	Not Detected		
Mech Linit	ار					

Mech. Unit : N/A Zone : Waiting #2 Test Site : Knob, Remote

Sample #	Sample Type	Date	Time	Results	Units
188344	SARS-CoV-2/2019 n-CoV-2	5/12/2020	2:05 pm	Not Detected	

Mech. Unit : N/A

Zone : Waiting Room #1

Test Site : Desk, Keyboard, Phone


Sample #	Sample Type	Date	Time	Results	Units
188342	SARS-CoV-2/2019 n-CoV-2	5/12/2020	1:52 pm	Not Detected	

Method of Analysis: EDLab SOP-7-27(RT-qPCR)

1) The result applies to the specific surface from where samples was collected.

2) This test is not for Clinical Diagnostics.

The results in this report apply only to the sample(s) specifically listed above and tested at Environmental Diagnostics Laboratory. Unless otherwise noted, samples were received in good condition. Laboratory-prepared Quality Control (QC) samples are analyzed with the samples routinely; however, unless a blank (control) is received, the result for the control is not compared.





Client: <u>Turning Point of Tampa</u> Jobsite: <u>Turning Point of Tampa</u> Location: <u>6227 Sheldon Road</u> PACS ID#: <u>07146</u> Work Order #: <u>025828</u>

End of Report